

# Effects of H<sub>2</sub>S on Steel Lift Station



**Steel has been totally eaten away in places**



After Abrasive Blasting  
and Preparation of Steel





After application of  
100 Mils of Raven 405



Back in Service